

Phase Marks
(See-through Holes)

Phase Marks
(See-through Holes)

<Ring-S>

<Ring Guide>

5 Screws

(S-Side)

(T-Side)

<Ring-S>

<Ring Guide>

<Ring-T>

